

Prop Scan[®] Condition Report

PROP DOCTOR'S LLC

3227 B RUSSELL STREET, THUNDERBOLT
GEORGIA 31404

Phone: 912695-0131

Mobile:

Toll Free:

Fax:

Report No. **Gratitude**
9 Job Number: **2100596A**
Boat Name:
Notes:
Design: **No Design**

No. of Blades: **5**
Markings:
Diameter: **28.000 ins**
Mean Pitch: **35.139 ins**

Serial Number:
Measured Date: **21/06/21**
Printed Date: **21/06/21**
Technician:

ISO 484/2

DOES
NOT
Conform


☒ Local Pitch
☒ Section Pitch
☒ Blade Pitch

☒ Sum of adjacent Local Pitches
☒ Difference of adjacent Local Pitches

Prop Scan Enhanced Propeller Standards

DOES
NOT
Conform

☐ Correct Pitch Distribution
☐ Increase/Decrease RPM
☐ Match Engine RPM
☐ Correct Camber
☐ Correct Face Shape
☐ New Face Camber Design
☒ Minimums NOT Applied



This Propeller **DOES NOT** conform to ISO 484/2 Class S

ISO 484/2 Tolerances on Pitch
Radii .3 .4 .5 .6 .7 .8 .9 .95

Prop Scan[®] Condition Report

PROP DOCTOR'S LLC

3227 B RUSSELL STREET, THUNDERBOLT
GEORGIA 31404

Phone: 912695-0131

Mobile:

Toll Free:

Fax:

Report No. Customer: **Gratitude**
9 Job Number: **2100597A**
Boat Name:
Notes:
Design: **No Design**

No. of Blades: **5**
Markings:
Diameter: **28.000 ins**
Mean Pitch: **35.078 ins**

Serial Number:
Measured Date: **21/06/21**
Printed Date: **21/06/21**
Technician:

.....

DOES
NOT
Conform

Sum of adjacent Local Pitches
Difference of adjacent Local Pitches

☒ ☒

ISO 484/2
Local Pitch
Section Pitch
Blade Pitch


☒ ☒ ☒

Prop Scan Enhanced Propeller Standards

DOES
NOT
Conform

Correct Pitch Distribution
Increase/Decrease RPM
Match Engine RPM
Correct Camber
Correct Face Shape
New Face Camber Design
Minimums NOT Applied

☐ ☐ ☐ ☐ ☐ ☐ ☒



This Propeller **DOES NOT** conform to ISO 484/2 Class S

ISO 484/2 Tolerances on Pitch
Radial .3 .4 .5 .6 .7 .8 .9 .95